

# WIRING HARNESS CHAFING MAY CAUSE ENGINE STALL

## Article Text

1993 Volkswagen Corrado

For Volkswagen Technical Site: <http://vw.belcom.ru>

Copyright © 1998 Mitchell Repair Information Company, LLC

Wednesday, March 22, 2000 09:28PM

### ARTICLE BEGINNING

#### NHTSA RECALL BULLETIN

Model(s):	1992 Volkswagen Corrado
	1993 Volkswagen Corrado
Campaign No:	93V102000
Number of Affected Vehicles:	4300
Beginning Date of Manufacture:	1991 AUG
Ending Date of Manufacture:	1992 NOV

#### VEHICLE DESCRIPTION:

Passenger cars equipped with a VR6 engine.

#### DESCRIPTION OF DEFECT:

An engine compartment electrical wiring harness may have been routed too close to a sheet metal edge. The wiring can become damaged during normal vehicle operation due to chafing, resulting in an electrical short.

#### FAULT:

Chafes, Excessive wear, Scored

#### SYSTEM:

Electrical system.

#### CONSEQUENCE OF DEFECT:

If a short occurs, either the engine could stall or the radiator fan could stop operating causing the engine to overheat. Either condition could result in a vehicle accident.

#### CORRECTIVE ACTION:

Reroute and secure various wiring harnesses inside the engine compartment.

#### ADDITIONAL INFORMATION:

The National Highway Traffic Safety Administration operates Monday through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.

### END OF ARTICLE