

LOOSE CRUISE CONTROL CABLE MAY NOT RETURN TO IDLE

Article Text

1987 Volkswagen Quantum/Quantum Syncro
For Volkswagen Technical Site
Copyright © 1998 Mitchell Repair Information Company, LLC
Sunday, March 19, 2000 01:46AM

ARTICLE BEGINNING

NHTSA RECALL BULLETIN

Models: 1987 Volkswagen Quantum/Quantum Syncro
1987 Volkswagen Vanagon
1988 Volkswagen Quantum/Quantum Syncro
1988 Volkswagen Vanagon
1989 Volkswagen Vanagon
Number of Affected Vehicles: 300
Beginning Date of Manufacture: 1987 AUG
Ending Date of Manufacture: 1988 DEC

VEHICLE DESCRIPTION:

Van camper type vehicle.

DESCRIPTION OF DEFECT:

When using the cruise control the accelerator cable tension may allow the cable to sag and become entangled with the water pipe bracket impeding its return to idle position.

FAULT:

Design

SYSTEM:

Cruise control.

CONSEQUENCE OF DEFECT:

Failure to return to idle position could lead to an accident.

CORRECTIVE ACTION:

The present accelerator cable bracket will be replaced.

ADDITIONAL INFORMATION:

The National Highway Traffic Safety Administration operates Monday through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.

END OF ARTICLE