

# AXLE SHAFTS TROUBLE SHOOTING

## Article Text

1987 Volkswagen Quantum/Quantum Syncro

For Volkswagen Technical Site

Copyright © 1998 Mitchell Repair Information Company, LLC

Sunday, March 19, 2000 01:02AM

### ARTICLE BEGINNING

Drive Axles

FWD TROUBLE SHOOTING

CONDITION	POSSIBLE CAUSE	CORRECTION
AA		
Grease Leaks	Joint boot torn, split or or cracked	See DISASSEMBLY in FWD AXLES SHAFTS article
Clicking Noise on Cornering	Damaged or worn outboard joint	See DISASSEMBLY in FWD AXLES SHAFTS article
Clunk Noise on Acceleration	Damaged or worn inboard joints	See DISASSEMBLY in FWD AXLES SHAFTS article
	Transaxle gears or bearings	See DISASSEMBLY in FWD AXLES SHAFTS article
Vibration or Shudder on	Sticking, damaged or worn joints	See DISASSEMBLY in FWD AXLES SHAFTS article
	Excessive alignment or spring height	See DISASSEMBLY in FWD AXLES SHAFTS article
Squealing or Humming	Insufficient or Improper Joint Lubrication	See DISASSEMBLY in FWD AXLES SHAFTS article
	Wheel Bearing Problem	See HUB & BEARING ASSEMBLY in FWD AXLES SHAFTS article
AA		

### END OF ARTICLE